

# SEALKOTE ON DETERIORATED ASPHALT SURFACE



SEALKOTE application on most deteriorated surface at the rate of 1 Kg per SqMt done on 3<sup>rd</sup> May 2012



As can be seen the uncoated surface on the left has almost lost all binding of asphalt



Application of SEALKOTE done on 150 SqMts of deteriorated surface having maximum traffic movement and maximum wear and tear



Next day of SEALKOTE application, visible surface undulations where asphalt has degraded on the right half of the asphalt road next to the concrete part



SEALKOTE application with squeeze, visible undulation of the rough surface like alligator back, final stages of wear



SEALKOTE application complete most of the coating has been absorbed by the porous and worn out surface



Surface as on 1<sup>st</sup> August 2014, same condition as on the date of application after two seasonal rains no further damage, the gravel is still intact and SEALKOTE has held it together